



# SeaQuest Status:

- Intermittent Beam-DAQ (Cherenkov) software issue introduced. Now fixed.
  - A crate controller CPU (ROC15) needed replacement yesterday
  - *Otherwise smooth data collection!*
- 
- New Station I drift chamber still in Lab 6 - we'd like to install during shutdown. However, HV shorting 300V below 2KV goal. *Progress:* problem seems to be localized to one distribution board. Loose wire fragment possible.



all protons (G2Sem)

protons below intensity threshold

protons below threshold & DAQ live

Last  
week

## Production data taking

